



NAV-AIDS LTD.



T A T G R O U P

TRANSPORT-CIVIL

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|--------------------------------------|--------------------|----------------------|--|--|---|--------------------------------------|
| Airbus A-300 | P52298-4 | 42.000 | 33410AB-125-4 | | PT15229 | AD300-30 |
| Airbus A-300 & 310 | P74418-4 | 851HV | 33410AB-125-4 (Cleco type) | | PT421-418 | AD300/310-851 |
| Airbus A-300 & 310 | P74418-4 | 851HV | SS31003-4 (Bar type) | S31082-4 (Bar type) | PT421-418 | ADA310-947 (RVSM) |
| Airbus A-300 & 310 | P63307M1-4 | 45.000 C16254AA | 33410AB-125-4 (Cleco type) | | 300-1110 | AD310-300MS ADA310-945 (RVSM) |
| Airbus A-300 & 310 | P63307M1-4 | 45.000 C16254AA | SS31003-4 (Bar type) | S31082-4 (Bar type) | 300-1110 | ADA310-946 (RVSM) |
| Airbus A-320, 318,319 &321 | P99320M1-4C | 50620 C16195AA | SS32092-4 (Bar type) | 532084M1-4 (Bar type) 33410ABB-125* (Cleco type) | PT19932 | ADA320-723 ADA320-945 (RVSM) |
| Airbus A-320, 318,319 & 321 | P99320M1-4C | 50620 C16195AA | 33410AB-125-4 33410ABB-125* (Cleco type) | 33410A47-125-4 (Cleco type) | PT19932 | ADA320-612 ADA320-946 |
| Airbus A-320, 318, 319 & 321 | P75701-4C | 0851HL | SS32092-4 (Bar type) | 532084M1-4 (Bar type) | PT17570 | ADA320-845 (RVSM) |
| Airbus A-330 & 340 except 500 Series | P75701-4 | 851GR 851 HL | S34093-4 (Bar Type) 33410ABB-125* (Cleco type) | | PT17570 | ADA330-340-612 ADA330-340-945 (RVSM) |
| Airbus A-330 & 340 all Series | P75701-4 | 851GR 0851 HL | S34093-4 (Bar Type) | S34104-4 (Bar Type) | PT17570 | ADA 330-340-946 |
| Airbus A-330&340 | P75701-4 | 851 GR 0851HL | 33410AB-125-4 33410ABB-125* (Cleco type) | | PT17570 | ADA330-340-723 |
| Airbus A-380 | P99380-4CK1 | | SSS11380-4C-4C-4C Standby S38024-4C | Standby P75701-4CK1 | PT19938 PT17570 | ADA380-945 |
| Boeing 707 | P14789-4 | 851T & 851CM | 33410M-125-4 Alt. Static Adaptor | 21298-370-4 | PT11478 | ADA707-612 |
| Boeing 717 | P15589M1-3 | 8S1AK | 334105A5-125-4 33410SAS-125B* | Alternate Static 33410SAS-90-4 33410SAS-90B* | PT11558M1 | ADA717-612 |
| Boeing 727- 100 | P14789-3 | 851T & 851CM | 33410M-125-4 | | PT11478 | ADA727-612 |
| Boeing 727- 200 | P14789-3 | 851T & 851CM | 33410LH-125-4 | EPR Adaptor 21298-170-4 | PT11772 | ADA927-180 |
| Boeing 737- 100, 200 300, 400 & 500 | PSS22300-3-4-4 | 856AE 8 & 13 | 33410LH-125-4 | Elevator Feel P14789-4 | PT12230 953-161 | AD953-7 |

Barfield Inc.
 4101 NW 29th Street.
 Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



TRANSPORT-CIVIL

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---------------------------|------------------------------|---|---------------------------------------|---|---|--------------------------|
| Boeing 737-600, 700 & 800 | P75701M2-3 (High Temp) | 851FJ1 851HT | 33410LH-125-4 | Vacu-Grip Assy 421-8971 Elevator Feel P14789-4 | PT17570 | ADA737-678 |
| Boeing 747-100, 200 300 | PSS44600M-3-4-4 | 856CC | 33410LH-125-4 | | PT14460 | AD967-47 |
| Boeing 747- 400 | PSS44600M2-3-4-4 (High Temp) | 856RE 3 & 4 | 33410LH-125-4 | | PT14460M1 | AD967-47M |
| Boeing 7475P | PSS44600SP-3-4-4 | 856KB 7 & 8 | 33410LH-125-4 | | PT44601 | AD967-47SP |
| Boeing 757 | P75701-3 | 851FJ | 33410LH-125-4 | 33410MC-125-4 Pressurization Port Test Adaptor P18815DM-4 P1 Adaptor Rolls Royce Eng. RR211-535E4 | PT17570 PT757-161 PT11881M | ADA757-612 LK757-723 |
| Boeing 767 | P5576700-3-4-4 | 856LU-RFT 856LU 1 & 2 | 33410LH-125-4 | | PT17670 | ADA767-612 |
| Boeing 767 | P5576700M2-3-4-4 (High Temp) | 856LU | 33410LH-125-4 | Vacu-Grip 421-8971 | PT17670 | ADA767HT-612 |
| Boeing 777 | P77796HT-3 (High Temp) | 856LU | 33410LH-125-4 | Pressurization Port Test Adaptor 33410MC-125-4 Vacu-Grip Assy 421-8971 | PT17779 | ADA777-612 |
| Convair 580 | P14789CA-4 | 831-02 | 33410-125-4 | | PT11882 | |
| DC-8 | P15589M-3 | 851AK A34580 00 003 A34570 00 003 Kollsman | 33410-70-4 | | PT11558 | ADA853-8 |
| DC-8L | P15589M-3 | 851AK A34580 00 003 A34570 00 003 Kollsman | 44521 -70-4 | Alternate Static Test Adaptor 21298-225-4 | PT11558 | |
| DC-8-63 & 71 | P15589M-3 | 851AK 851CU | 44521 -70-4 | Standby Pitot P99870-4 Alternate Static 21298-225-4 21298-225B* | PT11558 PT19987 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



TRANSPORT-CIVIL

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|-----------------------------------|--|---|---|---|---|--|
| DC-8-70 Passenger Freighter | P15589M-3 | 851AK 851CU | 33410-70-4 44521-70-4 | Standby Pitot P99870-4 Alternate Static 21298-225-4 21298-225B* | PT11558 PT19987 | |
| DC-8-72 | P15589M-3 | 851AK 851CU | 33410-116-4 | Standby Pitot P99870-4 Alternate Static 21298-225-4 21298-225B* | PT11558 PT19987 | |
| DC-9 | P15589M-3 | 851AK A34580 00 003 A34570 00 003 Kollsman | 33410-90-4 33410-90B* or 33410-125-4 33410-125B* | 1. Rudder Limiter P62261M-4 2. EPR Adaptor 63610-4 3. Pressurization Venture Throat Adaptor 1018 4. Outflow Valve Adaptor 22315-4 | PT11558 | ADA853-9 AD842-2C Rudder Throw Limiter Test Set |
| DC-10 | P25890-4 P52287M-4 | H7054 851DK | 33410LH-125-4 or 33410LH-90-4 | | PT12589 PT15228 | ADA853-10 |
| Lockheed 1011 | PSS55711-3-4-4 PSS55711 MI -3-4-4 (no safety compartment) | 856CR | | Alternate Static Test Adaptor 21298-370-4 | PT15571 PT15571 528-161 | 1011-319 |
| Lockheed Electra 188 | P85144-4 | | 21298-370-4 | | PT18514 | |
| MD-11 | P52287M-4 | 851DK | 33410LH-90-4 33410LH-90B* or 33410LH-125-4 33410LH-125B* | | PT15228 | ADAMD11-612 |
| MD-80 & MD-90 | P15589M1-3 | 851AK | 33410SAS-90-4 33410SAS-90B* | | PT11558M1 | ADAMD80-612 |

RVSM Testing

Nav-Aids Ltd. (RVSM) Air Data Accessories Kits contain all adaptors and hoses required to enable the connection of all static main and standby positions either individually or simultaneously as required.

For exact air data test procedures for each aircraft type, please refer to the Aircraft Manufacturers Maintenance Manual.

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|-----------------------------------|------------------------|--|---------------------------------------|---|---|--------------------------|
| Aero Commander | P14789CA-4 | PH506L&R | 33410S-90-4 | | PT11882 | |
| Astra SP & SPX | 18821-3 | 851Y 851W | SS40998M-1125-4 SS40998MB-1125* | | PT11882 | ADC988GAL-723 (RVSM) |
| Astra SPX (Gulfstream 100) | 18821-3 | 851Y 851W | SS40998M-1125-4 SS40998MB-1125* | | PT11882 | ADC988GAL-723 (RVSM) |
| ATP | P88257-4H | 853 BV | 21298L-180-4H 21298BL-180* | | PT18825 | ADATP612 |
| ATR42 ATR72 ATR42-500 | P22942M1-4 | 49380 Badin Crouzet | 33410HH-125-4 33410HB-125* | | PT12294 | ATR42-612 |
| ATR42 ATR72 ATR42-500 | P74418-4 | 0851JA | 33410HH-125-4 33410HB125* | | PT421-418 | ATR42-723 |
| AVRO RJ85 | P14600-4 | 853JE | SS88146-4 SS88146B* | A.S.I. STATIC 21298M2-182-4 21298M2-182B* | PT11460 | ADRJ85-612 |
| BAC-111 | P85144-4 P40951-A-4 | 851EU 393600002 Kollsman 853BS | 21298-245-4 | | PT18514 PT14095 | |
| BAE146 | P14600-4H | 853JE 853BJ 853JK | SS88146-4H SS88146B* | A.S.I. STATIC 21298M2-182-4 21298M2-182B* | PT11460 | ADRJ85-612 |
| BD100 CL300 | PSS73260-3-4-4 | 0856WC 0851LM | 33410S-70-4 | Standby Pitot P75701-3 | PT17326 PT421-5705 | BD100-945 (RVSM) |
| Beech A100 Bonanza Baron | 18821-3 | AN5812 | SKA100-4 | | PT11882 | |
| Beech 90 | 18821-3 | AN5812-1 | SKA100-4-4 | | PT11882 | KING-945 (RVSM) |
| Beech 200 Beech 300 | 18821-3 | AN5812 PH502 3 & 5 Beech P/N 50-384040-5R | SKA100-4-4 | | PT11882 | KING-945 (RVSM) |
| Beech Jet 400 | P14789CA-4 | PH1100-MM | 33410-60-4 | | PT11882 | ADA400-945 (RVSM) |
| Beech Jet 400A Beech Jet 400XP | P14789CA-4 | PH1100-MU | 33410-70-4 33410B-70* | | PT11882 | ADA400A-945 (RVSM) |
| Beech 1900 | PSS88340-3-4-4 | 856MG 1 & 2 | SKA100-4 | | PT18834 | ADA1900-612 |
| Beech Premier 1 | PSS99451-4-4-4 | 0856UH 1 & 2 | | | PT421 -451 | PREMIER 1-94S (RVSM) |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---|--------------------|---|--|--|---|---|
| Beech Starship | PSS88364-3-4-4 | 856NU2-FT1&2 BEECH P/N 122-384001-2 | | 33410MX-67-4 Standby | PT18836 | ADASS-612 |
| Beechcraft King Air | 18821-3 | 50-384040-3 50-384040-5 | SKA100-4-4 | | PT11882 | KING-945 (RVSM) |
| Bombardier Global Express | PSS73260-3-4-4 | 856TT | | | PT17326 | ADGE95-612 |
| Canadair CL215 | 18821-4 | | 21298L-225-4 21298LB-225* | | PT11882 | CL215-612 |
| CL300 BD100 | PSS73260-3-4-4 | 0856WC 0851 LM | 33410S-70-4 | Standby Pitot P75705-3 | PT17326 PT421 -5705 | BD100-945 (RVSM) |
| Canadair CL415 | 18821-4 | | 21298LCM-225-4 21298LCMB-225* | | PT11882 | CL415-612 |
| Canadair CL600 | PSS62148M-3-4-4 | 856KV 7 & 8 | 33410-70-4 | | PT12148 | AD601-612 AD601-945 (RVSM) |
| Canadair CL601 | P5562148M-3-4-4 | 856KV 7 & 8 | 33410-70-4 | | PT12148 | AD601-612 AD601-945 (RVSM) |
| Canadair CL-604 | PSS73259-3-4-4 | 856KV 9 & 10 851HF | 33410MX-67-4 33410B-67* | STANDBY PITOT P75701-3 | PT17325 | ADC604-612 ADC604-945 (RVSM) |
| Canadair Regional Jet | PSS73259-3-4-4 | 856KV 9 & 10 851HF | 33410S-70-4 33410S-70B* | STANDBY PITOT P75701-3 421-BCA Drain Hole cover | PT17325 PT17570 | ADCRJ-612 ADCRJ-945 (RVSM) |
| Casa 212 | P549742M-3-4 | AN5814 | | | PT14974 | ADA212-612 |
| Casa 212 | P14789CA-3 | PH1100-1-1HY | SKA100-4-4 | | PT11882 | |
| Casa 235 | PSS88235-3-4-4 | 856NC 1 & 2 | | | PT1 8823 | ADA235-612 ADA235/295- 945 (RVSM) |
| Casa 295 | PSS88235-3-4-4 | 856NC | | | PT1 8823 | ADA23S/295- 945 (RVSM) |
| Cessna 208 Caravan | PS47699-3-4 | PST300- 2S&2SA | | | PT1 4769 | |
| Cessna 425 & 441 Conquest | PS47699-3-4 | 0721105-18 | SKA100-4 | | PT14769 | |
| Cessna single Engine 150/170/180 Series Cessna 210 Cessna T206H | P96255-3 | | 33410-62-4 or SKA100-4 | | PT19625 | |
| Cessna 406 Reims | 18821 -4 | | SKA406-4-4 | | PT11882 | |
| Cessna Ultra & Encore | P86892-3 | | 33410FFAB-125-4 33410FFAB-125B* or 33410C1T-190-4 | | PT18689 | CITC-945 (RVSM) |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---|----------------------------|---------------------------------------|--|---------------------------|---|---|
| Cessna CJ Citation Jet 525 Cessna Citation Citation Jet II | P86892-3 | | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna Citation VI | P86892-3 | | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna Citation VII | P86892-3 | | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna 750 Citation 10 | P86892-3 | | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna Citation Excel Sovereign | 18821-3 | | 33410FFAB-125-4 33410FFAB-125B* | | PT11882 | CITC-945 (RVSM) |
| Cessna Citation 1 500 & 501 Citation 2 550 Citation 3 650 | P86892-4 | AN5812 PH502 | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna Citation 550 Bravo | P86892-3 | | 33410FFAB-125-4 | | PT18689 | CITC-945 (RVSM) |
| Cessna Citation Model 560 | P86892-4 | AN5812 PH502 PH1100RW& | 33410FFAB-125-4 33410FFAB-125B* | | PT18689 | CIT-612 CITC-945 (RVSM) |
| Cessna Citation V S/N 1-248 S/N 249 on | P86892-3 P86892-3 | | 33410C1T-190-4 33410CIT-190B* 33410FFAB-125-4 33410FFAB-125B* | | PT18689 PT18689 | CITC-945 (RVSM) CIT-612 CITC-945 (RVSM) |
| Cessna Mustang | P75705-3 | 0851LN | 33410FFAB-125-4 33410FFAB-125B* | | PT421 -5705 | MUSTANG-945 (RVSM) |
| Cirrus SR20/22 | 18821-4 | | SKASR20-4 | | PT11882 | |
| CL300 BD100 | P5573260-3-4-4 | 0856WC 0851LM2 | 334105-70-4 | Standby Pitot P75701-3 | PT17326 PT421- 5705 | BD100-945 (RVSM) |
| Dash 7 | P22201-3 | PH1100-1-DH | S62190-4 S62190B* | | PT11882 | ADH7-612 |
| Dash 8-100/200/ 300 Dash 8-400 | P22201-3 PSS22202-3-4-4 | PH1100-1DH C14135AA&BA C16193AB | S51089-4 S51089B* | Standby PS22203M-3-4 | PT11882 PT14097 Static Pre-Test Unit PT421-202 PT421-203M | DH8-7-612 DH8-723 Combined Kit DH8-834 |
| Diamond DA20/40/42 | PS56620-4-4 | 65797-07 | | | PT15662 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



T A T G R O U P

COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|------------------------|--|--------------------------------|--|--|---|------------------------------------|
| Dornier 228-201 Series | 18821-4 | P/R-603/2/5 | S44328L-225-4 S44328LB-225* S44328S-225-4 S44328SB-225* | | PT11882 | ADA228-612 |
| Dornier328 | P75701-4 | 851GW | S44328L-225-4 S44328LB-225* S44328S-225-4 S44328SB-225* | | PT17570 | ADA328-612 ADA328-945 (RVSM) |
| Dornier328 Jet | P75701-4 | 851GW | S44328L-225-4 S44328LB-225* S44328S-225-4 S44328SB-225* | | PT17570 | ADA328-612 ADA328-945 (RVSM) |
| Eclipse 500 | APA94520-4-4-4 P22201-4 | | | PS35210-4-4 | PT421-4520 PT11882 PT421-5210 | ADA500M-945 (RVSM) |
| Embraer 120 | PSS97865-3-4-4 | 856NB1-FT1 | | | PT19786 | ADA120-612 |
| Embraer 110 | 18821-4 | AN5812-1 | S34146-4 S34146B* | | PT11882 | ADA110-612 |
| Embraer 121 | P29932-4 | ANS811-1 | SKA100-4 | | PT11882 | |
| ERJ 135 & ERJ 145 | P75701-3 | 856GW 856NF | S34146-4 S34146B* | Standby Pitot PSS97865-3-4-4 | PT17570 PT19786 | ADA145M-612 ADA145M-945 (RVSM) |
| ERJ 170 & ERJ 190 | APA97632-3-4-4 | 0857CU | S34146-4 | CPAM-532 CPAM Test Assy | PT421-632 | ERJ 170/190-945 (RVSM) |
| Embraer CBA-123 | PSS97865-3-4-4 | 856NB1-FT1 | | | PT19786 | ADA120-612 |
| Falcon 10 | P22942M1-4 OR PSS61587-3-4-4 | 50520 33790/20 856NA | SSS4S10-300-4 SS54510B300* | 21298-245-4 Standby Static | PT12294 PT16158 | ADAF10-945 (RVSM) |
| Falcon 20 | P55517M1-4 P85144-4 PSS28286-3-4-4 | 50520 851 EU 856LR 1 & 2 | S43419-295-4 S4341 9B295* | | PT15551 PT18514 PT12828 | |
| Falcon 20F | P85144-4 | 8S1EU A44420-00-002 | S54520-4 554520B* | | PT18514 | |
| Falcon 50 | P55517M1-3 | 50520 | SS44111 P-60-4 SS44111 PB60* | 21298L-225-4 21298LB-225* Standby Static | PT15551 | ADAFS92-723 ADAFS92-945 (RVSM) |
| Falcon 200 | PSS28286-3-4-4 | 856LR 1 & 2 | | 21298-225-4 21298B-225* Standby Static | PT12828 | ADAF200-61 2 ADAF200-945 (RVSM) |
| Falcon 900 | P55517M1-3 | 50520 | SS44111 P-60-4 SS44111 PB60* | 21298L-225-4 21298LB-225* Standby Static | PT15551 | ADAFS92-723 ADAFS92-945 (RVSM) |
| Falcon 2000 | P55517M1-3 | 50520 | SS44111 P-60-4 SS44111 PB60* | 21298L-225-4 21298LB-225* Standby Static | PT15551 | ADAF592-723 ADAF592-945 (RVSM) |
| Falcon F7X | APA97634HTR-4C APA97634HTL-4C | 0857CV | | | PT421-7634 | ADAF7X-945HT (RVSM) |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.

COMMUTER & CORPORATE



T A T G R O U P

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|--|------------------------------|--|--|-------------------------------------|---|-----------------------------------|
| Fokker F-27 European Version | PS91227-3-4 | J1-150-27 | | | PT19122 | |
| Fokker F-27 US Version | P29932-4 | PH506, 504 | 33410-70-4 or 33410-125-4 | | PT11882 | |
| Fokker F-28 | P80128-4 | 853JB 2-810-A030 853BR 2-786-A030 | 21298-780-4 21298B780* 33410F-80-4 | | PT10128 | F28-612 |
| Fokker 50 | PSS88235-3-4-4 | 856PD 1 & 2 856PF | | | PT18823 | F50-612M |
| Fokker F-100 | P80128-4 | 853JB 2-810-A030 853BR 2-786-A030 | 21298-780-4 33410FF-80-4 | | PT10128 | ADAF100-612 |
| Fokker F-70 | P80128-4 | 853JB 2-810-A030 853BR 2-786-A030 | 21298-780-4 33410FF-80-4 | | PT10128 | ADAF100-612 |
| Galaxy (Gulfstream 200) | 18821-3 | 851Y 851W | 33410HHS-70-4 | 532-4900 Vacu-Grip | PT11882 | ADC988GAL-723 (RVSM) |
| Grob G120/G115TA | PS47699-3-4 | | | | PT14769 | |
| Gulfstream 1 | P29932-4 | PH506L&R | 21298-225-4 21298B-225 | | PT11882 | |
| Gulfstream 2 Gulfstream 3 Gulfstream 4 Gulfstream 400 | P15589M1-3 | 851AK 851GE | 21298GRM6-180-4 21298GRM6B-180* 21298GRM6-190-4 21298GRM6B-190* | Cabin Pressurization 21298-270-4 | PT11558M1 | ADAG24-612 ADAG5-945 (RVSM) |
| Gulfstream 3 | P15589M1-3 | 851AK 851GE | 21298GRM6-180-4 21298GRM6B-180* | Cabin Pressurization 21298-270-4 | PT11558M1 | ADAG3-612 |
| Gulfstream 5 | PSS99451HT-3-4-4 (High Temp) | 0856TK | | | PT421-451 | ADAG5-612HT ADAG5-834HT (RVSM) |
| Gulfstream 100 (ASTRA SPX) Gulfstream 150 | 18821-3 | 851Y 851W | SS40998M-1125-4 SS40998MB1125* | | PT11882 | ADC988GAL-723 RVSM |
| Gulfstream 200 (Galaxy) | 18821-3 | 851Y 851W | 33410HHS-70-4 | 532-4900 | PT11882 | ADC988GAL-723 (RVSM) |
| Hawker Horizon | 18821-4 | PH502 | 21298-7MM-4 | | PT11882 | |
| Hawker 4000 | P75701-3 | 0851JE 0856UN | 21298GR20-190-4 | P573458-3-4 | PT17570 PT421-458 | ADA4000-945 (RVSM) |
| Hawker 4000 | P75701M2-3 (High Temp) | 0851JE 0856UN | 21298GR20-190-4 | (High Temp) PS73458HT-3-4 | PT17570 PT421-458 | ADA4000-945HT (RVSM) |
| HS125 Early Models | P41140M-4 | G20/150/27 and Subs. (.750 Dia.) | 21298GR55M3-180-4 21298GR55M3B-180* 21298M3-180-4 21298M3B-180* | 21298-250-4 Stall Warning Test | PT14114 | ADA125-200 |
| HS125-600 | P40951M-3 P39392-4 | 853JA 853JF N512-125-28 N514-125-28 | 21298GR55M3-180-4 21298GR55M3B-180* 21298M3-180-4 21298M3B-180* | 21298-250-4 Stall Warning Test | PT14095 PT13939 | ADA125-945 (RVSM) |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|----------------------------------|---------------------------------|-------------------------------|--|--|---|-------------------------------------|
| H5125-700 H5125-800 | P40951M-3 | 853JA 853JF | 21298GR55M3-180-4 21298GR55M3B-180* 21298M3-180-4 21298M3B-180* | 21298-250-4 Stall Warning Test | PT14095 | ADA125-612 ADA125-945 (RVSM) |
| H5125-1000 | PSS88340-3-4-4 | 856RV 853KD | | Standby Pitot P14700-4 21298-250-4 Static Vent System Tester 21298ST-182-4 | PT18834 PT11470 | AD1000-612 ADA1000-945 (RVSM) |
| HS-748 | P41140M-4 | | 21298-245-4 | | PT14114 | |
| Jetstar 1 | 18821-4 | | 33410S-70-4 or 33410-125-4 | | PT11882 | |
| Jetstar 2 | PSS48297-3-4-4 P537186M-3-4 | 856DF 5 & 6 856DF7&8 | | | PT14829 PT13718 | ADAJ2-612 |
| Jetstar 731 | PS63639-3-4 | 856EB 3 & 4 | 33410S-70-4 or 33410S-125-4 | | PT1 6363 | |
| Jetstream HP137MK1 | 18821-4 | PH502 | 21298-7MM-4 21298-7MMB* | | PT11882 | |
| Jetstream 31 | 18821-4 | | 21298M-225-4 21298MB-225* | | PT11882 | ADA31-612 |
| Jetstream 41 | 18821-4 | | 562190M1-4 562190M1B* | | PT11882 | ADAJ41-612 |
| Jetstream 41 MOD 41303 A&B | 18821-4 | | 212985T-182-4 21298NFB-182* | | PT11882 | ADAJ41-723 |
| Learjet 20 | 18821-4 or PSS61587-3-4-4 | PH502 856NA1+2 856NR7+8 | SKA100-4 | | PT11882 PT16158 | |
| Learjet 24 & 25 & 35 | P14789CA-4 | II-IU PH1100 | UJA100-4-4 | | PT11882 | |
| Learjet 31/35 50/60 Series | P5561587HT-3-4-4 (High Temp) | 856NA 1 & 2 856KR 7 & 8 | | | PT16158 | ADA60-945HT (RVSM) |
| Learjet 45 Series | PSS72698-3-4-4 | 0856TJ | | | PT421-698 | L45-61 2 L45-945 (RVSM) |
| Learjet 45 Series | P5572698HT-3-4-4 (High Temp) | 0856TJ | | | PT421-698 | U45-945HT (RVSM) |
| Learjet 60 Series | PSS61587-3-4-4 | 856NA 1 & 2 856KR 7 & 8 | | | PT16158 | ADA60-723M ADA60-945 (RVSM) |
| Maverick Jet | 18821-4 | PH502-12 | SKA100-4 | | PT11882 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---|-------------------------|--|--|--------------------------------|---|---------------------------------|
| Metroliner3 | P14789CA-4 | | 33410S-70-4 33410S-70B* | | PT11882 | ADAM3-612 |
| MOONEY | 18821-4 | AN5812 | SKA100-4 | | PT11882 | MOONEY-612 |
| MU2B-20 MU2B-25 MU2B-35 MU2B-40 MU2B-60 | P14789CA-4 | PH506L&R PH506L&R PH506L&R PH1100L&R PH1100L&R | SKA100-4 | | PT11882 | |
| MU-300 | P14789-4 | | SKA100-4 | | PT11882 | |
| PC-12 | P62271M-4 | AN5814-2 | 33410S-70-4 33410S-70B* | Vacu-Grip Assembly 532-4900 | PT16227 | PC12-723 |
| PHENOM 100 (Embraer) | PS88755-3-4 P75705-3 | 101469-4 0851 LP | | SKAEMBPH1-4-4 | PT421-8755 PT421-5705 | PHENOM-945 |
| Piaggio P-180 | P15589M1-3C | 851AK | 33298L-182-4 33298LB-182* 33298S-182-4 33298SB-182* | 421-8971 Vacu-Grip Assembly | PT11558M1 | ADA180-612 ADA180-945 (RVSM) |
| Piper Aerostar | PS49742M-3-4 | AN5816 PST300-2 | | | PT14974 | |
| Piper Malibu Mirage | 18821 -4 | PH502-10 | SKA100-4 SKA100B* | | PT11882 | |
| Piper Malibu Meridian | 18821 -4 | PH502-10 | SKA100-4-4 SKA100BB* | | PT11882 | |
| Piper Saratoga II Mirage | 18821-4 | PH502-1 0 | SKA100-4 SKA100B* | | PT1 1882 | |
| Piper Seneca III | PS56620M2-4-4 | | | | | |
| Piper Seneca V | 18821-4 | PH502-10 | SKA100-4 SKA100B* | | PT11882 | |
| Piper Warrior III | PS56620M2-4-4 | | | | | |
| Piper Archer III | PS56620M2-4-4 | | | | | |
| Piper Arrow | PS56620M2-4-4 | | | | | |
| Piper Aztec | PS49742M-3-4 | PST503 | | | PT1 4974 | |
| Piper Aztec C | P547741 M-4-4 | AN581 6 1 & 2 round section PST 300A | | | PT1 4774 | |
| Piper Seminole | PS56620M2-4-4 | | | | | |
| Piper Cheyenne PA31 | 18821-4 | PH502 | 33410-62-4 | | PT11882 | |
| Robin DR400/500 | 18821-4 | AN5812 | 21298-150-4 21298B-150 | | PT11882 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



COMMUTER & CORPORATE

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|----------------------------|--------------------|------------------------------|--|---|---|--------------------------------------|
| Sabreliner 60 & 75 & 85 | PSS26075-3-4-4 | 856DL 1 & 2 | | | PT12607 | ADA60-75-612 ADA65-70-945 RVSM |
| Saab 340 | PSS88340-3-4-4 | 856ML | | | PT18834 | ADA340-612 |
| Saab 2000 | PSS88340-3-4-4 | 856ML | | | PT18834 | ADA340-612 |
| Shorts SD3-30 SD3-60 | P14789CA-4H | PH1100-1R | S34146-4H S34146B* | | PT11882 | ADA36-612 |
| SJ30-200 | PSS99451-3-4-4 | 0856UJ2 PH1100-1- INVF | 33410S-160-4 (Cabin Pressure Test Adaptor) | Alternate Pitot Test Adaptor P14789SJ-3 | PT421-451 PT11882 | SJ30-2-612 |
| TB-10 TB-20 | P29932-4 | AN5812 | S43510SM-150-4 S43510SBM-150* | | PT11882 | |
| TBM-700 TBM-850 | P29932-4C | AN5812 | S43510LM-150-4 S43510LBM-150* S43510SM-150-4 S43510SBM-150* | | PT11882 | ADA700-612 |
| T-28Trojan | P22201-3 | AN5813-1 PH500 | | | | |
| Twin Otter | P29932-4 | PH506 | 21298-180-4 | | PT11882 | AD422-16 |
| Turbo Commander 680V | P14789CA-4 | PH506L&R | 33410S-92-4 | | PT11882 | |
| Viscount | 18821-4 | AN5812 | 33410-70-4 33410-B70* | | PT11882 | |
| Westwind 1121 & 23 | 18821-3 | 851Y 851W | SS51062-4-4 SS51062B* | | PT11882 | |
| Westwind 2 1122 & 24 A | 18821 -3 | 851Y 851W | SS40998M-1125-4 SS40998MB-1125* | | PT11882 | ADC988GAL- 723 (RVSM) |
| Westwind 1124 & 266 | 18821-3 | 851Y 851W | SS32266-4-4 SS32266B* | | PT11882 | |
| Westwind 1125 Astra | 18821-3 | 851Y 851W | SS40998M-1125-4 SS40998MB-1125* | | PT11882 | ADC988GAL- 723 (RVSM) |
| Westwind 1124 | 18821-3 | 851Y 851W | SSS9516-4 SS9516B* | | PT11882 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



EUROCOPTER HELICOPTERS

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data /RVSM Accessories Kit |
|--|--------------------------|--------------------------------|---------------------------------------|-----------------------------|---|--------------------------------|
| Allouette Lama | P85144NAR-4 | 25527 | | | PT18514 | |
| AS350/355 Civil | P35055-4 | 39500 | 21298-150-4 21298B-150* | | PT13505 | ADA350-5-612 |
| AS550/555 Military | P35055-4 | 39500 | 21298-150-4 21298B-150* | | PT13505 | ADA350-5-612 |
| AS330 Puma | P33044-4 | 25527 type 31 | | | PT13304 | |
| BO105 | P18105-4 | PR608 PR603-2-1 PR6130-1 | SKA100-4 | | PT11882 | ADABO/105-612 |
| BK-117 | 18821-4 | PH502-BKC | S34146-4 S34146B* | | PT11882 | ADA117-612 |
| EC 120 Colibri | P88494-4 | 33494 | SKAEC120-4 | | PT421-494 | EC120-612 |
| EC 130 | P88494-4 | 33494 | 21298-140-4 | | PT421-494 | EC130-612 |
| EC 135 | 18821-3 | PH502BKC PH500-BKW | 33410SML-70-4 33410S-70B* | 532-4900 Vacu-Grip-Assy | PT11882 | EC135-723 |
| EC 145 | 18821-3 | PH502BKC PH500-BKW | 33410SML-70-4 33410S-70B* | 532-4900 Vacu-Grip-Assy | PT11882 | EC135-723 |
| EC 155 | P88494-3 | 33494 | SSS15536-4-4-4 | | PT421-494 | EC155-612 |
| EC 225 | PNS22596-3-4 | 54755 | SKAX30MM-4-4-4 | | PT421-596 | EC225-725-612 |
| EC225MKII Plus EC725MKII Plus (Military) | PNS22596-4 | 54755 | 55526647-4-4-4 | | PT421-596 | EC225/725 PLUS-723 |
| EC 332 MK I Super Puma MK I | P88494-3 | 46380-2 | SKAX100-4-4-4 | | PT421-494 | EC332MKI-612 |
| EC 332 MK II Super Puma MK II | PNS22956-3-4 | 54755 | | | PT421-596 | EC332MKII-723 |
| EC 365 N2/N3 Dauphine | P88494-3 | 46380-2 | SKAX30MM-4-4-4 | | | EC365-565-723 |
| EC 565 Cougar | P88494-3 | 46380-2 | SKAX100-4-4-4 | | PT421-494 | EC332MKI-612 EC365-565-61 2 |
| EC 532 MK I Panther | P88494-3 | 46380-2 | SKAX100-4-4-4 | | PT421-494 | EC365-565-612 |
| EC 635 MK I Military | 18821-3 | PHSO2-BKC PHSOO- BKW | 33410SML-70-4 33410S-70B* | 532-4900 Vacu-Grip- Assy | PT11882 | EC135-723 |
| EC 725 HH 65 | PNS22596-3-4 P88494-3 | 54755 46380-1 | SKAX30MM-4-4-4 SKAX30MM-4-4-4 | | PT421-596 | EC225-725-612 EC365-565-723 |
| NH90 | PSSS904S3-3-4-4-4 | 0856TU 0851JN | | Standby Pitot P65508-3 | PT421-453 PT421-508 | ADANH90-612 |
| Tigre | P75703-3 | 0851HM | 21298-150-4 21298-B150* | | PT421-703 | Tiger-612 |

Barfield Inc.
4101 NW 29th Street.
Miami, FL 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



MISCELLANEOUS HELICOPTERS

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---|-----------------------------|--|---------------------------------------|------------------------|---|--------------------------|
| Agusta 109A | PS82369-4-6 | 369D | | | PT18236 | ADA109-612 |
| Agusta 109A II | PS82369-4-6 | 369D | | | PT18236 | |
| Agusta 109C Agusta Power Agusta A109K Agusta Grand | PS44129-4-6 | 0850L9 0850L10 | | | PT14412 | ADA109C-612 |
| Agusta A109BA AB212 | P22201-4 | AN5813 | 33410S-70-4 33410S-70B* | | PT11882 | ADA109BA-612 |
| Agusta A109 NEXUS | PS59872-3-4 | 855GR | | | PT421-9872 | ADA109C-723 |
| Agusta 109E | PS44129-4-6 | 0850L9 | | | PT14412 | ADA109C-612 |
| Agusta 109EOA | P22201-4 | PH500 AN5813-1 781- 02 | | | PT11882 | ADA109EOA-612 |
| Agusta 119 Koala | PS59872-3-4 | 0855GR | | | PT421-9872 | ADA119A-612 |
| Agusta 129 | PS44129-4-6 | 0850L8 & 9 | | | PT14412 | ADA129-612 |
| Agusta 609 | P14789-3 | 856PV1 | 33410-70-4 33410-B70* | | PT11882 | ADA609-723 |
| Agusta AB139 | PSS88139-3-4-4 | 0856WD | | | PT421-8139 | ADA139-612 |
| Agusta AB412 | P22201-4 | AN5813-1 | 33410S-70-4 33410S-70B* | | PT11882 | ADA412-612 |
| AH-1Z | P22201-4 | AN5813-1 | S78425-4 | | PT11882 | ADABH1-612 |
| AH-64D Apache | 18821-4 | AN5813-1 | S33073-6 | | PT11882 | AH64D-612 AH64D-723 |
| Bell AHIS | 18821-4 | AN5813-1 | 33410S-70-4 33410S-70B* | | PT11882 | |
| Bell AHIW | PS82369-4-6 PS49742M-4-6 | 369D-012-022 AN5816 | | | PT1 8236 PT14974 | |
| Bell 204C | PS82369-4-6 18821-4 | 369D AN5813-1 | 33410S-70-4 33410S-70B* | | PT18236 PT11882 | |
| Bell 206 Jet Ranger | P22201-4 | PH500 | 33410S-70-4 33410S-70B* | | PT11882 | ADA206-612 |
| Bell 212 Civil | P22201-4 | PH500 AN5813 | 33410S-70-4 33410S-70B* | | PT11882 | ADAB212-612 |
| Bell 212 Military | PS49742M-4-6 | AN5816-2 PST300-A PST300-2 Type 651 B | | | PT14974 | |
| Bell 214 | P22201-4 | PH500 | 33455M-70-4 33433M1-70 | | PT11882 | ADA214ST-612 |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



MISCELLANEOUS HELICOPTERS

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---------------------------------|---------------------------------|------------------------------------|--|--|---|---------------------------------|
| Bell 222 | P22201-4 | PH500 | 334105-70-4 | | PT11882 | ADA222-612 |
| Bell 230 | P22201-4 | PH500 AN5813 | 33410S-70-4 33410S-70B* | | PT11882 | ADA230-612 |
| BELL 407 BELL427 BELL 429 | P22201-4 | PH500 | 33410S-70-4 33410S-70B* | | PT1 1882 | ADA427-612 ADA427-612 NBR |
| BELL 412 (CH146 Griffen) | P22201-4 | | 33410M-70-4 33410MB-70* | Static Blanking Adaptor P89212B Vacu-Grip Assy 532-4900 | PT11882 | ADA412-723 - |
| BELL 430 | P22201-4 | PH500 | 33410S-70-4 33410S-70B* | | PT1 1882 | ADA230-612 |
| Blackhawk Nighthawk | PSS59101-4-6-6 | 856HM 7 & 8 | | | PT15910 | ADA60A-612 |
| CH-47D | 18821-3 | AN5813-2 | 21298M-370-4 21298MB-370* | Vacu-Grip Assy 532-4900 | PT11882 | ADA47D-612 |
| CH-53E Superstallion | P549742M-4C-6C | AN5816 | | | PT14974 | ADA53E-612 |
| CH113 | P30993-4 P41493-4 | 923-02 | SSS77663-4 SSS77663B* SS88113-4 SS88113B* | | PT13099 PT14149 | CH113M-612 |
| CH-124 Seaking | PS47741M-4-6 PS62862-4-6 | | | | PT1 4774 PT1 6286 | |
| CH-136 | 18821-4 | AN5812 | 33410S-70-4 | | PT11882 | AD452-2 |
| EH 101 | P75602-4 | 851HN 1 & 2 | 21298-8MM-6 21298B8MM* | | PT17560 | ADAEH1O1-945 |
| Enstrom 480 | 21298-290-4 | PS00217 | SKAENS480-4 | | PT421 -217 | |
| H-1 | P22201-4 | AN5813-1 | S78425-4 | | PT11882 | ADABH1-612 |
| H1 + UH1 Military | P582369-4C-6C P547741M-4C-6C | 369D AN5816-2 PST300- ASR | | | PT18236 PT14774 | ADAH1-612 |
| Ka-32 | 21298-370-3 | | S8301 7-4 | | | ADAK32-612 |
| Lynx MK88 | P80128M1-4 | N53-84-1 | 21298-300-6 | | PT18012 | |
| MD 900 Explorer | 18821-4 | PH500-BKC | SKA100-4 (Single) SKA100-4-4 (Dual) | | PT11882 | |
| MD 600 & 500 Series | | | SKA100-4 | | | |
| MH-2000 | P29932-4 | 506 L&R | S34146-4 S34164W | | PT11882 | ADAMH200-612 |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



MISCELLANEOUS HELICOPTERS

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|----------------------------|--------------------|----------------------|---------------------------------------|------------------------|---|--------------------------|
| Mi-8 | PS11218 | | | | PT11121 | |
| MI 17 | PS00217 | | | | PT421-217 | |
| Night Raider | P88905-4 | | | | PT18890 | |
| OH58C | P29932-4 | PH500 | | | PT11882 | |
| OH58D | P22201-3 | | 33410S-70/ 33410SB-70* | | | OH58D-612 |
| S61N | PS47741 M-3-4 | | | | PT14774 | ADAS61N-612 |
| SH2G H2 Kaman | P86892-3 | AN5813 | SKA2G-4 | | PT18689 | SH2G-612 |
| S-64 | PS49742M-4-6 | AN5816-2 | | | PT14974 | |
| S-76 | PSS50902-3-4-4 | 856LK1 | 50891M-4 50891BM1 * | | 421-3437 | S76-612 |
| S-92 | PSSS90453-3-4-4-4 | 856 TU 0851JN | | Alternate P65508-3 | PT421-453 PT421-508 | S92-723 |
| SH2 | 18821-4 | AN5813 | 21298-475-4 | | PT11882 | |
| SH60B | P62261M-4 | 851AH | 33410SH-70-6 33410-B70* | | PT16226 | SH60B-612 |
| UH60L UH60A&HH60D | PSS59101-4-6-6 | 856HN 7 & 8 | | | PT15910 | ADA60A-612 |
| VH3D | PS47741M-4C-6C | | | | PT14774 | VH3D-612 |
| V-22 | PSS89022-4-6-6SL | 856PV1,2,3,4- FT1 | | | PT18902 | V22-723 |
| V-22 | PSS89022HT-4-6-6S | 856PV1,2,3,4- FT1 | | | PT18902 | V22HT-723 |
| Westland W30 Series 100 | PS49742M-4-6 | 856EH-1 01 | | | PT1 4974 | |
| 366SST | P20036-3 | 853BY 853JE | 21298-140-4 21298B-140* | | 421-036 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.



MILITARY AIRCRAFT

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|------------------|---|------------------------|---------------------------------------|-----------------------------|---|---|
| AMX | PSS88340-4-6-6 PS64437-4-6 (Pilot Boom) | 856MPZ-FT1 856EB | | | PT18834M P16443 | ADAMX340-612 |
| A-6E | PS38052-4C-6C | 855R-1 | | | PT13805 | ADA6E-612 |
| A-7E | PS49163-4-6 | 856W-4 | | | PT14916 | |
| A-4 | PS66953-4-6 PS55824-4-6 | 855DT&852J 855DY | | | PT16695 PT15582 | |
| A-10 | PS88555-4 | 855DM | | | PT18555 | |
| Aermacchi M-346 | PSB85709M-3-4 | SLZ8160-14 | | | PT421-709 | ADAM346-612 |
| Aermacchi 339 | PS35891-4-6 P14789CA-4 | 852AC & 852AD PH504 | SS44339-4 SS44339B* | | PT13589 PT11478 | AD339-612 |
| Alpha Jet 2 | PSS59262-3-4-4 P60373-3 | | S48151-4 S48151SAS-4 | | PT421-9262 PT421-0373 | ALPHA-612 |
| AV8B Harrier | PS89154-4H-4H | 856MB | | | PT18915 | ADA8B-612 |
| AV8B/T10 Harrier | PS89154-4H-4H | 856MB | | | PT18915 | AV8B-T10-612 |
| AV8B US Navy | PS89154-4C-6C | 856MB | | | PT18915 | ADA8B-612 |
| B1B Bomber | PSA99186-4-6-4 | 857AC1-FT1 | | | PT19918 | AD1B-612 |
| Boeing 707 | P14789-4 | | 33410S-125-4 21298-370-4 | | PT11478 | ADA707-612 |
| C2A | PSS87123M-4-6-6 P29932M1-4 | 856RN1 & 2 PH557 | S60191-6 | | PT18712 PT11882 | C2A-61 2 ADAC2A-612 ADAC2A-612-1 |
| C-9 | P15589M1-3 | 851AK | 33410-90-4 | | PT11558M1 | ADAC9-945 |
| C.130A, B&E | P29932-4 | | 33410LH-140-4 | | PT11882 | ADA130H-612B |
| C.130H & Subs | PSS88130-4-6-6 | 856NM | | | PT18813 | ADA130J-723 ADC130-723 ADA30H-612 |
| C130J | PSS88130-4-6-6C | 856NM | | | PT18813 | ADA130J-723 |
| C5A | PSS85011 M-4-6-6 | 856AT-8B | | | PT421-850 | ADAC5-612 |
| C27J | P99527-3 | C16329AA C16330AA | S21287-4 | Standby Pitot P63307M1-3 | PT19952 300-1110 | ADAC 27J-945 |
| C.17 | PSS98237-4-6-6 | 856PY1 | 33410A-160-4 | | PT19823 | ADA17-612 |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.

MILITARY AIRCRAFT



T A T G R O U P

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|--|---|----------------------|---------------------------------------|---|---|--------------------------|
| C.141 A&B | P516859-4-6 | 856LL1 & 2 | | | PT11685 | AD41B-612 |
| CC-109 Cosmopolitan | 18821-4 | | 21298-225-4 | | PT11882 | AD442-3 |
| CC138 Twin Otter | P29932-4 | | 21298-180-4 | | PT11882 | AD422-16 |
| CC-117 Falcon | P77894-4 | | 33410LH-90-4 | Alternate Static Test Adaptor 21298-225-4 | PT17789 | AD422-2 |
| CC-115 Buffalo | P29932-4 | | | | PT12993 | AD422-4 |
| CC-130 Hercules | P29932-4 | | 33410LH-140-4 | | PT12993 | AD422-6 |
| CF-101 | PS66822-4-6 | 852A Type MA1 | | | PT16682 | |
| CF-5 | PSS55611 M-4-6-6 | 855B-3 | | | PT15561 | |
| CF-104 | PS55104-4-6 | 8550K TRU-125/A | | | PT15510 | |
| CF-116 | PSS55611 M-4-6-6 | 855B-3 | | | PT15561 | |
| CP-121 Tracker | PA36901-4 | PH506L&R | 21298-180-4 | | PT13690 | AD422-9 |
| CP-107 Argus | 18821-3 | PH500 AN581 3-1 | 33410-70-4 | | PT11882 | AD422-12 |
| CP-140 Aurora | P85144-4 | 851 EU | 21298-370-4 | | PT18514 | AD280 |
| CT-134 Musketeer | PA36921-4 | | 33410S-70-4 | | PT13692 | AD444-12 |
| Dash 8 & Dash 8 Navigation Trainer | P22201-3 | | S51089-4 S51089B* | | PT11882 PT14097 | CT142-723 |
| E3 | P17720-4 | 851CM | 33410AB-125-6M 33410B-125M* | | PT11478 | ADAE3-612 |
| E2C | P29932M1-4 | PH557 | S59080-6 | | PT11882 | ADE2C-612 |
| E-2D | APA97632-4-6-6 | 2O15G1H1B | | CPAM-643 | PT421-632 | ADAE2D-945 |
| EA6B | P593425-4C-6C | 856CD | | | PT19342 | ADA6B-612 |
| EFA Fighter | PD2183M1-4 AOA96502-4 Angle of Attack | | SD1072M1-4 | | PT2000 | EFA-834 |
| F4-C&D | P75732-4 | 851-171 | 21298-170-4 | | PT17573 | ADAF4C-612 |
| F4-E | PS52752-4-6 | 855AN-2H | | | PT15275 | |
| F5-E&F | PS54548-4-6 | 855CF-1 | | | PT15454 | |
| F.14 | PS82314-4C-6C | 856DR1 & 2 | | | PT18231 | ADA14-612 |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.

MILITARY AIRCRAFT



T A T G R O U P

| Aircraft Type | Pitot Test Adaptor | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adaptors | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|------------------------|---|--|---------------------------------------|--|---|--------------------------|
| F.14 | AP93914-4 (Alpha Probe) | | | | APT19391 | APA14-723 |
| F.15 | PSS60615M1-4-6-6 | 856GD1 & 2 | | Pitot Duct Adaptor P18815D-4 Static Duct Adaptor 53510 -310-6 | PT16061 PT11881 | ADA15-723 |
| F.16 | PS77900-4-6 | 855EG | 33422-70-6 (C9241-1) | 421-7900 (Vacu Grip) | PT17790 | ADA16-612 |
| F.16 | APA28988 Alpha Probe APA17887-4-6 System Purge Adaptor | | | | PT12898 | APAF16-723 |
| F-16 E-F (Block 60) | PSB85709M-3-4 | SLZ28150-14 | | | PT421 -709 | |
| F.18 CF18 Canadian | PS27961M-4-6 | 856KJ | | | PT421-9610 | ADA781-F18 |
| F.18 E/F | PS27818-4C-6C | | | | PT421-818 | ADF18EF-612 |
| F.18 US | PS27961M-4C-6C | 856KJ | | | PT421-9610 | ADA781-F18 |
| F.18 Australian | PS27961 M-4-6 | 856KJ | | | PT421-9610 | ADA781-F18 |
| F.86 | PS40640-4-6 | AN5814 | | | PT14064 | |
| G-222 (C.27) | P15589M1-4 | 851GB | S21287-4 S21287B* | | PT11558M1 | ADAC27-612 |
| Hawk 128 | APA97634HT-4-4-4 PS52437M1HT-4-4 | 855JG | | | PT421-7634 PT15243M1 | H128-612 |
| Hawk 52 & 100 | PS52437M-4H-4H | 855BR&BM | 33410-70-4H 33410B-70B* | | PT15243 | H52-612 |
| Hawk 200 | PS20092-4H-4H | O856PK 4 & 3 | 33410-61-4H 33410-61B* | | PT12009 | ADA200-612 |
| HU25 Falcon | PSS44485-3-4-4 | 856HK 1&2 | | | PT14448 | HU25-612 |
| Jaguar | PS64457-4-6 | 856NN1 & 2 | | | PT63-7270 | ADA63-612 |
| KC-135 | PS99016-4-6 | 856AG | 33410AB-125-6KC 33410B-125KC* | 421-7900 (Vacu Grip) | PT19901 | ADA135-612 |
| OV-10 | PS92692-4-6 | PST800-2 | | | PT19269 | LK10-723 |
| PC-7 & PC9 | 18821-4 | AN5812-1 | S33014-6 S33014B* | | PT11882 | ADAPC719-612 |
| PC-21 | P62261M-4C | O851JT | SS21025-4-4 | | PT16226 PTS21025 (Static Plate) | PC21-612 |
| P3 Orion | P85144-4C | 851EU B264 4000 002 A264 40 00 002 | 21298-370-6C 21298TB-370* | | PT18514 | ADAP3-612 |
| Predator | 18821-4 | ST300-2PT | SKA100-4 | | PT11882 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT



NAV-AIDS LTD.

MILITARY AIRCRAFT



T A T G R O U P

| Aircraft Type | Pitot Test Adapter | Pitot Probe Part No. | Static Test Adapter Blanking Adapter* | Miscellaneous Adapters | Pitot Pre-Test & Assembly Integrity Fixture | Air Data Accessories Kit |
|---------------|---|-----------------------------------|---------------------------------------|------------------------|---|--------------------------|
| S-105 | PS48953-4-6 | | | | PT14895 | ADA105-612 |
| S3A | PSS31570-4-6-6 | 0856 0E5 | | | PT421-570 | |
| S-35 | PS93535-4-6 | | | | PT19353 | |
| SA227 C26D | P14789CA-4 | | 33410S-70-4 33410S-70B* | | PT11882 | ADAM3-612 |
| T/45 | PS52437M1-4-6 PS63548-4-6 (Pitot Static Boom) | 855JG 0092BH3 | | | PT15243 M1 | T45-612 |
| T50 | PSB85709M-3-4 | SLZ8140-14 | | | PT421-709 | T50-612 |
| T.133 | P29932-4 | | S20133-4 | | PT11SS2 | ADAT133-612 |
| T/46A | PSS88946-4-6-6 | 856MW-FT1&2 | | | PT18894 | T/46A-612 |
| Tornado | PS53326-4H-6H P40951-4H | 855EG-BV(Nose) 853BT-JC (Side) | 53510-346-4H 53510B-346* | | 421-3326 421-0951 | |
| Tucano | 18821-4 | | 33410-70-4H 33410-B70* | | PT11882 | ADTUC-612 |
| U2 | P20706-4 | 102DG2U-2 | SS44222-6 | | PT421-706 | |

Barfield Inc.
4101 NW 29th Street.
Miami, Fl. 33142
Phone Line: (305) 894-5400
Fax Line: (305) 894-5401

AIRCRAFT MAINTENANCE REPAIR OVERHAUL & SUPPORT